



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D2182B060
Job Sheet 201766



Part No: D2182B060

Job Qty: 5 pcs

Part Name: Clamp Cushion Black 6.0 "Long



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 10/10/19

Job Tracking No:

Due Date: 10/24/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV D IPP: B 99.03.02 Re-format DM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Packaging 1 - Pklt Kit	5 pcs	10/24/19		0.00	0.00	Packaging 1 - 1		
							Packaging 1 - 2		
							Packaging 1 - 3		
							Packaging 1 - 4		
							Packaging 1 - 5		
							Packaging 1 - 6		
							Packaging 1 - 7		
							Packaging 1 - 8		
							Packaging 1 - 9		
							Packaging 1 - 10		
							Packaging 1 - 11		
							Packaging 1 - 12		
							Packaging 1 - 13		
							Packaging 1 - 14		
							Packaging 1 - 15		
							Packaging 1 - 16		
							Packaging 1 - 17		
							Packaging 1 - 18		
							Packaging 1 - 19		
							Packaging 1 - 20		
							Packaging 1 - 21		
							Packaging 1 - 22		
							Packaging 1 - 23		
							Packaging 1 - 24		
							Packaging 1 - 25		
							Packaging 1 - 26		
							Packaging 1 - 27		
							Packaging 1 - 28		
							Packaging 1 - 29		
							Packaging 1 - 30		
							Packaging 1 - 31		



Container No: S223975



Part: D2182B060

Job No: 201766

Serial No/Batch: S223975

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Date: 10/18/19

Plex 10/10/19 11:09 AM Dart.lajeunesse.marie

110 QC 5	5 pcs	10/24/19	0.00 0.00	Packaging 1 - 32	
				Packaging 1 - 33	
				Packaging 1 - 34	
				Packaging 1 - 35	
				Packaging 1 - 36	
				QC 5 - 10	
				QC 5 - 12	
				QC 5 - 17	
				QC 5 - 18	
				QC 5 - 19	
				QC 5 - 22	
				QC 5 - 24	
				QC 5 - 3	
				QC 5 - 43	
				QC 5 - 49	
				QC 5 - 51	
				QC 5 - 58	
				QC 5 - 68	
				QC 5 - 9	
				QC 5 - 50	
				QC 5 - 30	
120 Packaging 3-1 - Stock - B4B 5 pcs		10/24/19	0.00 0.00	QC 5 - 40	DAS OCT 21 2019 40 9-89
				QC 5 - 61	
				QC 5 - 81	
				Packaging 3 - 1 - B4B	
				Packaging 3 - 2 - B4B	
				Packaging 3 - 3 - B4B	
				Packaging 3 - 4 - B4B	
				Packaging 3 - 5 - B4B	
				Packaging 3 - 6 - B4B	
				Packaging 3 - 7 - B4B	
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	
				Packaging 3 - 19 - B4B	
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	Pc 57639
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	

10/10/2019

[Dart Hawkesbury] Job Sheet - Lajeunesse, Marie

130 QC 21 - SA	5 pcs	10/24/19	0.00 0.00	Packaging 3 - 36 - B4B	
				QC 21 - SA - 21	
				QC 21 - SA - 70	046
				QC 21 - SA - 53	21
				Broussard	2-39
					OCT 21 2019
Part Op 100 - (Pick Kit) Cut D2182B black rubber extrusion 6.0" long Descriptions: 110 - (QC5- Inspect part completeness to step on W/O) 120 - (Identify as per dwg & Stock Location: _____) 130 - (QC21- Final Inspection - Work Order Release)					
Job BOM					
Part / Item	Component Name	Quantity	Operation	Container	
D2182B	Rubber Cushion - Black (\$Per Foot)	2.5000 ft (.5 ea)	100-Packaging 1 - Pick Kit	F160459	
Job Allocations					
Operation	Component Part	Required	Inventory	Allocated	
100-Packaging 1 - Pick Kit	D2182B	3	4,140	0	
Part Specifications					
Specifications could not be found.					

Plex 10/10/19 11:09 AM Dart.lajeunesse.marie



Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

Route update only

NCR No. _____

Job: _____		DISPOSITION				DEPARTMENT/PROCESS				Engineering																																																																																									
Part No. _____		Rework Scrap Use-as-is				Cross tube Small Fab Finishing				Eng. (Non-AW) Prod. Eng. Coord. Rec/Store/Packaging				Water Jet Supplier Quality																																																																																					
Date: _____		Sequence #: _____		QTY Affected: _____		MRB (QS1042)																																																																																													
Description Work Order Deviation						Disposition																																																																																													
Root Cause <table border="1"><tr><td>Operator</td><td></td></tr><tr><td>Manufacturing Process</td><td></td></tr><tr><td>Equip/Tooling</td><td></td></tr><tr><td>Handling/Preservation</td><td></td></tr><tr><td>Material</td><td></td></tr><tr><td>Product Improvement</td><td></td></tr><tr><td>Process Improvement</td><td></td></tr><tr><td>Human Factors</td><td></td></tr></table>						Operator		Manufacturing Process		Equip/Tooling		Handling/Preservation		Material		Product Improvement		Process Improvement		Human Factors		FAULT CATEGORY <table border="1"><tr><td>Pressure/Forced</td><td></td><td>Contamination</td><td></td><td>Power Loss/Surge</td><td></td><td>Positioned Wrong</td><td></td></tr><tr><td>Bending</td><td></td><td>Misaligned/off center</td><td></td><td>Folio/Program</td><td></td><td>Outside Tolerance</td><td></td></tr><tr><td>Crushing</td><td></td><td>BOM/Route</td><td></td><td>Grain Direction</td><td></td><td>Drawing</td><td></td></tr><tr><td>Cracks</td><td></td><td>Broken/Damage/Defect</td><td></td><td>Weld</td><td></td><td>Finish</td><td></td></tr><tr><td>Crimp/Kink/Ripple/Wave/Twist</td><td></td><td>Incomplete/Unclear Instructions</td><td></td><td>Wrong Stock Pulled</td><td></td><td>Part Lost/Missing</td><td></td></tr><tr><td>Marks/Chatter</td><td></td><td>Drill Holes</td><td></td><td>Out of Sequence</td><td></td><td>Misread</td><td></td></tr><tr><td>Mislabeled</td><td></td><td>Fit/Function</td><td></td><td>Off-set/Set-up</td><td></td><td></td><td></td></tr><tr><td colspan="2">Other/Details:</td><td colspan="6"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td></tr></table>						Pressure/Forced		Contamination		Power Loss/Surge		Positioned Wrong		Bending		Misaligned/off center		Folio/Program		Outside Tolerance		Crushing		BOM/Route		Grain Direction		Drawing		Cracks		Broken/Damage/Defect		Weld		Finish		Crimp/Kink/Ripple/Wave/Twist		Incomplete/Unclear Instructions		Wrong Stock Pulled		Part Lost/Missing		Marks/Chatter		Drill Holes		Out of Sequence		Misread		Mislabeled		Fit/Function		Off-set/Set-up				Other/Details:														Completed By	
						Operator																																																																																													
						Manufacturing Process																																																																																													
						Equip/Tooling																																																																																													
Handling/Preservation																																																																																																			
Material																																																																																																			
Product Improvement																																																																																																			
Process Improvement																																																																																																			
Human Factors																																																																																																			
Pressure/Forced		Contamination		Power Loss/Surge		Positioned Wrong																																																																																													
Bending		Misaligned/off center		Folio/Program		Outside Tolerance																																																																																													
Crushing		BOM/Route		Grain Direction		Drawing																																																																																													
Cracks		Broken/Damage/Defect		Weld		Finish																																																																																													
Crimp/Kink/Ripple/Wave/Twist		Incomplete/Unclear Instructions		Wrong Stock Pulled		Part Lost/Missing																																																																																													
Marks/Chatter		Drill Holes		Out of Sequence		Misread																																																																																													
Mislabeled		Fit/Function		Off-set/Set-up																																																																																															
Other/Details:																																																																																																			
						Lead hand / Supervisor																																																																																													
								QC / QA Coordinator																																																																																											